

Testing of VAV Boxes

7th Floor:

Sr. No.	Wing Name	Location	VAV No.	Operational	Actuator Make	VAV Dia, mm	Max CFM	Min CFM	Thermostat	Remarks
1	IT Area	VP Cabin	1	No	Delta	150	400	40	Delta	Not working
2		SBIL / CPC / WS / 159	44(CAV)	No	Delta	300	1672	1667	-	all wires removed from VAV
3		Training room	40	No	Delta	300	1500	150	Delta	Not working
4		Training In-charge	16	Yes	Delta	150	350	35	Delta	
5		Digi Lab	38	Yes	Delta	250	1000	100	Delta	
6		IT Training room	41	No	Delta	300	1550	155	Honeywell	All wires disconnected and Thermostat not compatible
7		Mail Room	32	No	Delta	150	200	20	Delta	Not working
8		Administration	36	No	Delta	200	700	70	Delta	Not working
9		Rest room / Doctor's room								Not accessible

8th Floor:

Sr. No.	Wing ID	Location	VAV No.	Operational	Actuator Make	VAV Dia, mm	Max CFM	Min CFM	Thermostat	Remarks
1	D2	Meeting Room - Narmda	23	Bypass	Delta	150	500	50	Honeywell	Thermostat not compitable, Controller faulty
2		Meeting Room - Sindhu	15	Yes	Delta	150	350	35	Delta	
3		SVP & Head (New Business)	12	Yes	Delta	150	275	27	Delta	
4		Waman Gawade	13	Yes	Delta	150	275	27	Delta	
5		Near CMO Cabin	2	Thermostat not working	Delta	150	275	27	Honeywell	Leakages in joints, thermostat not compitable
6		CMO Cabin	4	Yes	Delta	150	275	25	Delta	
7		SBIL / CPC / WS / 348	49(CAV)	Yes	Delta	600	6650	6650	-	
8		SBIL / CPC / WS / 335	46(CAV)	Yes	Delta	400	3000	2295		
9		BMS Room	24	ON position	Delta	150	150	15	Missing	
10	D1	Meeting room - Brahmaputra	33	Yes	Delta	200	600	60	Delta	
11		EVP & Head (Digital and Innovation)	27	Yes	Delta	150	300	30	Delta	
12		EVP (Digital infra, Governance & Citso)	26	Yes	Delta	150	250	25	Delta	
13		SVP & EVP & Head (Digital and New Technologies)	5	Yes	Delta	150	250	25	Delta	
14		SVP & Head (Non Sales Enterprises Systems)	14	No	Delta	150	250	25	Delta	VAV Controller issue
15		SVP & Head (Resilient Operations)	25	Thermostat problem	Delta	150	250	25	Delta	Thermostat display issue
16		SVP & Head (Customer Direct Platform)	6	Yes	Delta	150	250	25	Delta	
17		SBIL / CPC / WS / 235	47(CAV)	Yes	Delta	400	3375	3370	Delta	
18		SBIL / CPC / WS / 210	50(CAV)	Yes	Delta	600	4275	4270	Delta	
19	E2	SBIL / CPC / WS / 667	52(CAV)	Yes	Delta	600	7100	7095	Delta	
20		SVP & Head (Group Operations)	17	Yes	Delta	150	350	35	Delta	
21		SVP & Head (Renewals & Customer Retentions)	30	Yes	Delta	150	210	27	Delta	
22		VP Cabin	3	Yes	Delta	150	270	27	Delta	
23		SVP & Head (Claims & Claim Fraud Management)	8	Yes	Delta	150	350	35	Delta	
24		SBIL / CPC / WS / 574	43(CAV)	Yes	Delta	250	1400	1395	Delta	
25		Meeting room - Godavari	29	Yes	Delta	150	400	40	Delta	
26		Meeting room - Kaveri	18	Yes	Delta	150	500	50	Delta	
27		Chief of Customer Service and Experience	22	Yes	Delta	150	500	50	Delta	
28	E1	EVP & Head (Customer Service and Experience)	28	No	Delta	150	300	30	Delta	VAV Actuator problem
29		SVP & Head (PS & LB Payouts)	7	Yes	Delta	150	350	35	Delta	
30		SBIL / CPC / WS / 419	51(CAV)	Yes	Delta	600	6750	6745	Delta	
31	F2	Cabin of Mr. Chandrashekhar M	5	Yes	Bellimo	150	400	0	Bellimo	bypass VAV
32		Deputy COO (On-boarding and Claims)	3	Yes	Bellimo	150	400	0	Honeywell	
33		Legal officer (Business Operations)	2	Yes	Bellimo	150	400	0	Cosmos	Thermostat Faulty (Room temperature not appearing)
34		Deputy COO (Renewal, Retention and Servicing)	4	Yes	Bellimo	150	400	0	Cosmos	
35		Meeting room - Tapi	1	Yes	Bellimo	150	400	0	Cosmos	
36		SBIL / CPC / WS / 716	48(CAV)	Yes	Delta	450	4060	4055	-	
37	F1	SBIL / CPC / FH / STR / 124	53(CAV)		Delta	600	4980	4975	-	
38		Dinning Area	9	Yes	Delta	200	800	80	Delta	
39		President's Study room	19	Yes	Delta	150	500	50	Delta	
40		SBIL / CPC / WS / 741	45(CAV)		Delta	350	2320	2315	-	
41		Visitor Lounge	20	No	Delta	150	500	50	Delta	Not working
42		MD & CEO	11	Yes	Delta	200	800	80	Delta	
43		President (Operatios & IT)	35	Yes	Bellimo	200	800	80	Honeywell	
44		COO Cabin	10	Yes	Delta	200	800	80	Delta	
45		VC Room - Yamuna	37	No	Delta	250	1000	100	Delta	Not working (wiring not connected)
46		Conference room - Ganga	39	Yes	Delta	300	1500	150	Delta	
47		CIO Cabin	34	Yes	Delta	200	800	80	Delta	
48		Meeting room	21	Yes	Delta	150	500	50	Delta	

9th Floor:

Testing of VAV Boxes

Sr. No.	Wing Name	Location	VAV No.	Operational	Actuator Make	VAV Dia, mm	Max CFM	Min CFM	Thermostat	Remarks
Sr. No.	Wing ID	Location	VAV No.	Operational	Actuator Make	VAV Dia, mm	Max CFM	Min CFM	Thermostat	Remarks
1	F2	F2 Wing cabin 8	25	YES	Delta	175	600	60		
2		SBIL / CPC / WS / 979	34	YES	Delta	600	5000	500		
3		Meeting room - Krishna	26	YES	Delta	175	600	60		
4		F2 Wing cabin 7	16	YES	Delta	100	200	20		
5		F2 Wing cabin 6	18	YES	Delta	100	200	20		
6		SBIL / CPC / WS / 941	31	YES	Delta	400	3000	300		
7		F2 Wing cabin 5	3	YES	Delta	100	200	20		
8		F2 Wing cabin 4	4	YES	Delta	100	200	20		
9		F2 Wing cabin 3	1	YES	Delta	100	200	20		
10		F2 Wing cabin 2	10	YES	Delta	100	200	20		
11		F2 Wing cabin 1	13	No	Delta	100	200	20		VAV not working
12		SBIL / CPC / WS / 918	29	YES	Delta	300	2000	200		
13	F1	Cabin #1	9	YES	Delta	100	200	20		
14		Cabin #2	2	YES	Delta	100	200	20		
15		Cabin #3	7	YES	Delta	100	200	20		
16		Cabin #4	11	YES	Delta	100	200	20		
17		Cabin #5	5	YES	Delta	100	200	20		
18		Cabin #6	6	YES	Delta	100	200	20		
19		BMS Room	NA	No	NA	NA	NA	NA		VAV not working
20		Cabin #7	17	YES	Delta	100	200	20		
21		Cabin #8	14	YES	Delta	100	200	20		
22		Cabin #9	8	YES	Delta	100	200	20		
23		Reception	NA	No	NA	NA	NA	NA		VAV not working
24		Cabin #10	12	YES	Delta	100	200	20		
25		Meeting room - Jhelum	28	YES	Delta	250	1000	100		
26		Meeting room - Chenab	23	YES	Delta	100	200	20		
27		Internal Ombudsman	27	YES	Delta	200	750	75		
28		SBIL / CPC / WS / 1123	32	YES	Delta	400	3500	350		
29		SBIL / CPC / WS / 1015	33	YES	Delta	600	5000	500		
30		SBIL / CPC / WS / 1011	35	YES	Delta	600	5000	500		
31		Café #1	30	YES	Delta	350	2400	240		
32		Café #2	22	YES	Delta	150	500	50		